

DWPC INSPECTION DIGITAL PHOTOGRAPH PHOTOCOPIES

Photo # 001
Date: May 8, 2013
Time: 11:10 a.m.
Taken By: Brian Rodely DWPC/FOS
Facility: Thole Ag, Inc.
Location: E of Middle Herd Building
Notes: This is photograph a
portion of the concrete
feedlot area. Note that the
buildings in the background
are equipped with
guttering.



Photo #: 002
Date: May 8, 2013
Time: 11:15 a.m.
Taken By: Brian Rodely DWPC/FOS
Facility: Thole Ag, Inc.
Location: S of High Herd Building
Notes: This is photograph a
portion of the concrete
feedlot area and one of the
concrete settling basins.
Note that the building is
equipped with guttering.



DWPC INSPECTION DIGITAL PHOTOGRAPH PHOTOCOPIES

Photo # 003
Date: May 8, 2013
Time: 11:45 a.m.
Taken By: Brian Rodely DWPC/FOS
Facility: Thole Ag, Inc.
Location: N of "pre-fresh" barn
Notes: This is a photograph of a gutter constructed to convey away from the buildings to the waste containment system.

Exemption 6 and Exemption 7(C)



Photo # 004
Date: May 8, 2013
Time: 12:00 p.m.
Taken By: Brian Rodely DWPC/FOS
Facility: Thole Ag, Inc.
Location: West of the concrete pit
Notes: This is a photograph of the concrete pit and sand storage area.



DWPC INSPECTION DIGITAL PHOTOGRAPH PHOTOCOPIES

Photo # 005
Date: May 8, 2013
Time: 12:15 p.m.
Taken By: Joe Stitely DWPC/FOS
Facility: Thole Ag, Inc.
Location: SW of earthen feedlot.
Notes: This is a photograph of the facility's "dry lot" earthen feedlot.



Photo # 007
Date: May 8, 2013
Time: 12:30 p.m.
Taken By: Joe Stitely DWPC/FOS
Facility: Thole Ag, Inc.
Location: SW of Concrete Pit
Notes: This is a photograph of tile that can be used to discharge livestock wastes. Note the box cut out of the retaining wall. At the time of the inspection, a sand bag was covering the tile inlet to prevent discharge.

